

EXHIBIT 1

There is a typographical error in the identification of the make and model of the antenna used by KCSM in the Facility Technical Data listed in the Licensing and Management System.

The antenna is listed as a DIE TUM-C5SP-14/60H-2-T-R.

It is actually a DIE TUM-C5SP-14/60-2-R-T.