

The station is experiencing technical problems with its transmitter. The station is working with the manufacturer to fix the problem, but will need to operate at reduced power while the problem is isolated and resolved.