

Resumption of Normal Operations; Request to Leave STA in Effect

On April 10, 2016, the licensee of W41DL-D discovered that the facility had begun operating again at its full licensed parameters. The licensee was making preparations to install the antenna specified in LMS STA File No. 0000022447 when the resumption of normal operations was discovered.

The licensee has been unable to determine how or why the facility has started again to operate at its normal parameters, and the licensee has monitored the operations for two weeks to try to determine whether the resumption is a fluke or is permanent. At this time, the licensee cannot determine with certainty whether the facility will remain operational at its full licensed parameters, and the licensee worries that the facility is likely to again fail to the condition that gave rise to the STA filing in LMS STA File No. 0000022447. For that reason, the licensee respectfully requests that the STA granted in LMS File No. 0000022447 remain in effect until its scheduled expiration date in early October 2017. Then, in the event of a further failure, the licensee would have the same antenna replacement option specified and granted in LMS STA File No. 0000022447 available to it without the need for expenditure of further Commission resources to re-evaluate the situation.

* * * * *