

Explanation of Reduced Power Operation

KNCT-DT, Belton, TX (FID 9754)

As explained in its previous Engineering STA (File No. 29468), KNCT is experiencing technical issues with its TV transmitter. The station can only operate at 50% power. This transmitter must be replaced when the station builds its repacked facility, therefore the station will continue to operate at reduced power until it constructs its repack facility. The station inadvertently did not renew its previous Engineering STA, therefore, it requests reinstatement and extension of this engineering STA nunc pro tunc.