



**Explanation for Reduced Power Operation
KSBY
Facility ID 19654
San Luis Obispo, CA**

KSBY recently experienced a problem with the inductive output tube in its main transmitter and it is currently operating at 50% of the licensed transmitter power output. KSBY expects that the transmitter manufacturer will be on-site within the next week to repair the transmitter; however, station personnel will monitor the situation and KSBY will apply for an STA if it appears the repair process is anticipated to take longer than 30 days.

**PROVIDING COMMUNICATION
SYSTEMS ENGINEERING**

CORPORATE OFFICE
1475 NORTH 200 WEST
POST OFFICE BOX 311
NEPHI, UT 84648

TEL: (435) 623-8601
FAX: (435) 623-8610

REGIONAL OFFICE
6197 MILLER RD., SUITE 1
SWARTZ CREEK, MI 48473

TEL: (810)-226-0750