

REASON FOR ENGINEERING STA REQUEST

W204CP WESTPORT, KY FAC #106487 is operating at low power after having a new antenna installed which is tuned incorrectly, and will not operate at full power. A new antenna has been ordered, and will be installed as soon as possible.