

## Justification

A lightning strike damaged the KYTI main antenna, requiring KYTI to operate using an auxiliary antenna at the same location. A replacement antenna has been ordered. However, the licensee is not currently able to access the antenna location due to inclement weather and, accordingly, requires an extension of STA to allow it time to access the location. Accordingly, KYTI respectfully requests special temporary authority to continue operating at 1.05kW – the highest power that the transmitter can produce under the current circumstances and a 50% reduction from KYTI's licensed power of 2.1kW – for up to six months.