

LOW PWR STA REQUEST

WIFF WINDSOR, NY FAC #2868

BLED-20100420AHS

10/6/23

WIFF is operating at reduced power, approximately 27% due to a faulty transmitter. Repairs will be made as soon as possible and the FCC will be notified when WIFF is operating normally again.