

**Resumption of Operations Notification**

In early October 2016, the licensee was able to restore W21CL to operating status. However, after operating at full power for less than a day, the facility shut down, and the licensee began to explore the cause of the problem, intermittently putting the station back on the air only to have it repeatedly cease operating. On October 20, the licensee was able to put the station back on the air at reduced power of approximately 1 kW. The station has now been operating consistently at reduced power since that time. After troubleshooting and diagnosing the situation, the licensee has determined that the transmitter needs a software upgrade in order to maintain full licensed power. Thus, for the time being, the station is operating at reduced power. Out of an abundance of caution, the licensee is also filing a reduced power notification immediately after filing the instant resumption of operations notification. If it appears that the reduced power operation will continue beyond 30 days, the licensee will file a request for STA.

\* \* \* \* \*