

General Information Exhibit: Justification for STA

This exhibit is to advise the Commission that KNPG-LD is operating at 1.1 kw ERP or 61.1% of authorized power. A lightning strike caused the Reject Load, Combiner and Power Amplifier to short out. The licensee is in the process of replacing the damaged components and is waiting for the combiner, which is coming from a factory in Brazil. The licensee respectfully requests special temporary authority to continue to operate at reduced power until the damaged parts are replaced and delivered to the station and the transmitter repair is complete. At this time it is expected that the repair will take approximately 60 to 90 days.

* * * * *