

As disclosed in its August 7, 2018 notification of reduced power, the station's copper heat exchanger coils on the primary transmitter ruptured and lost all the distilled cooling water. As a result, the station moved to a backup transmitter at low power. The station continues to attempt to locate a replacement heat exchanger or try to repair the transmitter. Thus, it requests authority to operate at reduced power with its backup transmitter with the facilities specified herein.