

Explanation for Reduced Power Operation

WTXL-TV

Facility ID: 41065

Tallahassee, FL

WTXL-TV recently began experiencing difficulties maintaining full transmitter power. After further investigation, station personnel suspect the transmitter has a bad IOT tube. The station is currently maintaining 40% of its authorized power. It is currently expected to take several weeks to complete the repairs; however, station personnel will monitor the situation and WTXL-TV will apply for an STA if it appears the repair process is anticipated to take longer than 30 days.