

WFQX-TV
Request for Engineering STA

The WFQX antenna network has been damaged resulting in an inability operate with limited power levels of between 5 and 10 percent, or between 10 and 20 kW ERP. The licensee is working to restore the station to full authorized parameters, but the tower is currently too iced to be safely climbed, a condition that is unlikely to change for several weeks.

Accordingly, special temporary authorization is requested for operation at reduced power until restoration work is completed and the station can be restored to full licensed operating parameters.