

Explanation

Due to two failed modules in the transmitter, the station is operating at low power (approximately 40% of authorized power). The modules have been sent for repair but there is only one company that repairs these modules. It is anticipated that the repair could take up to six months.

Grant of this STA will allow the station to continue to provide service to the public.