

ENGINEERING STA REQUEST-LOW POWER

KVJC GLOBE, AZ FAC #91804

The transmitter is experiencing power fluctuation; it is operating at about 50%. Engineers have been scheduled, and will make needed repairs/adjustments, and the FCC will be notified when repairs are complete.