

Special Condition #2

RF Hazard

The antenna is mounted on the side of a rooftop penthouse. Measurements were taken on the rooftop and on the floor immediately below the roof. The measurements show that the RF exposure levels are excessive near the penthouse and on the rooftop. Exposure levels do not exceed the guidelines on the floor below the roof.

The site manager has agreed to restrict access to the penthouse and rooftop when the auxiliary antenna is energized. There is a flashing light on the antenna and an antenna energized signal sent to the building monitoring system. Signs and chain barriers are used where appropriate. All individuals visiting the site will be required to carry a personal RFR monitor.