

## EXHIBIT 12A – SERVICE CONTOUR OVERLAP

The following map illustrates the existence of required 60 dBu contour overlap of the proposed and existing facility.

