


Radiotechniques

402 Tenth Ave. • PO Box 367 • Haddon Heights, NJ 08035-0367

Exhibit 12 Figure 4
Second and Third Adjacent Interfering Contour
Fred R and Evelyn K Morton
Oklahoma City, OK
June 2004

127 dbu Contour Distance Above Ground



No structures above ground on this chart.