

Antenna Technical Data Exhibit

The Applicant discovered a discrepancy in the antenna rotation in the construction permit downloaded from CDBS and the antenna rotation in the application for the underlying construction permit BMPDTA-20150219ABW for which this license to cover application is filed.

The antenna rotation in the construction permit downloaded from CDBS shows 20 degrees; however, the antenna rotation in the Engineering Data in CDBS (http://licensing.fcc.gov/cgi-bin/ws.exe/prod/cdbb/pubacc/prod/eng_tv.pl?Application_id=1671641) and in the application for construction permit shows 330 degrees.

The correct antenna rotation is 330 degrees.