

### Exhibit 1

This station's antenna support structure was acquired in 1998 as part of a larger transaction involving the station. The licensee removed all abandoned equipment from the support structure and now operates the tower at a reduced load. The licensee has not conducted a structural analysis because it has never been determined to be necessary. The licensee cannot confirm under which structural standard the tower was constructed.