

STA Request  
NPG of Monterey-Salinas CA, LLC  
KMUV-LP, Monterey, California

**General Information Exhibit: Justification for STA**

This exhibit is to advise the Commission that KMUV-LP is operating at 70% power as a result of a failure within the station's power amplifier. At the time of the instant request, the damaged part has been sent to the manufacturer for repair or replacement. Because it is taking longer than the licensee anticipated to repair (or replace), the licensee respectfully requests special temporary authority to continue to operate at reduced power until a repaired or replacement amplifier is returned to the station and installed in the transmitter.

\* \* \* \* \*