

Engineering STA Explanation

prepared March 2016 for

OTA Broadcasting (SFO), LLC

KAXT-CD Fac ID 37689

Channel 42 15 kW

KAXT is currently operating at 60% power due to a failed amplifier in the transmitter. The licensee has been in discussion with the amplifier manufacturer regarding repairs. There were no loaner units available from the manufacturer for this particular unit, so the amplifier must be repaired and replaced into the transmitter. The unit will be replaced shortly and KAXT will resume licensed ERP.