

COHEN, DIPPELL AND EVERIST, P. C.
CONSULTING ENGINEERS

RADIO-TELEVISION

1420 N STREET, N.W.

SUITE ONE

WASHINGTON, D. C. 20005

(202) 898-0111

DONALD G. EVERIST, PE
PRESIDENT

THOMAS G. LOCKE

CONSULTANT

ROBERT P. ECKERT, PE

JULIUS COHEN
(1913-1993)

RALPH E. DIPPELL, JR.
(1922-1992)

FACSIMILE

(202) 898-0895

E-MAIL:

CDEPC@COMCAST.NET

December 14, 2016

Ms. Marlene Dortch
Secretary
Federal Communications Commission
The Portals
445 12th Street, S.W.
Room TW-B204
Washington, DC 20554

Re: W31BX-D, Danville, Illinois
Facility ID 70853
Section 73.1560(d) of the Rules
Notification of Reduced Power Operation

Dear Ms. Dortch:

This letter is to advise that W31BX-D, Danville, Illinois (Facility ID 70853) is operating at reduced power. This power reduction is due to a transmitter equipment failure. W31BX-D operates on an assigned Channel 31 with a maximum directional ERP of 3.08 kW and a radiation center above mean sea level of 241 meters.

W31BX-D is operating at approximately 50% (1.04 kW) of licensed power. The problem RF equipment has been sent back to the manufacturer for repair. This transmitter manufacturer is undergoing restructuring and this lends a degree of uncertainty to its successful repair and return into operation.

The W31BX-D technical staff has been in further contact with the transmitter manufacturer and is hopeful that this RF equipment will be returned soon.


The FCC will be updated when the repair to the RF unit has been performed and has been installed and full power operation has been restored.

COHEN, DIPPELL AND EVERIST, P. C.

Ms. Marlene Dortch
December 14, 2016
Page 2

If there are any questions, please do not hesitate to contact this office.

Sincerely,



Donald G. Everist
Consulting Engineer for W31BX-D

DGE:cc

cc: Frank Brannock
Fred Vobbe
Jason Rademacher