

Notice of Reduced Power Operations

Station: WMFP, Facility ID # 41436, Lawrence, MA

December 21, 2016

On December 19, 2016 at 14:00 local time, the power level of the main transmitter of WMFP was reduced to approximately 72% of licensed power. The transmitter had been operating in an unstable manner, and after extensive troubleshooting local staff were unable to regain stability without reducing the operating power. A service call from the transmitter manufacturer will be required to resolve the issue, and that service call is not expected to occur until early January 2017. If normal operating power cannot be restored within 30 days, the licensee will request special temporary authority to continue to operate at reduced power until repairs are complete.