

Cross Hill Communications, Inc.
FRN 0021-4025-81
WYCU-LD, Facility ID 189163

REASON FOR GOING SILENT

High reflected power caused the transmitter to shut down. The preliminary diagnosis is that the power divider is damaged.

The station is awaiting cost estimates for repair. It is unlikely that repairs can be completed within 30 days, so the station is filing a combination notification of suspension of operations and request for an STA to remain silent.