

Justification for Request for Special Temporary Authority

KLBY-DT is presently operating at half power due to problems with the transmitter. The reduced-power STA engineering request is necessary while the licensee repairs the transmitter in order to return to full power.