

## TPO Calculation

100 FT LMR 400 LOSS = 1.187 DB

ANTENNA GAIN 1.26X

$50/1.26 = \text{POWER OUT COAX} = 40\text{W}$

WITH 1.187 LOSS THROUGH COAX, TPO IS THEN 53 WATTS