

KSMQ-TV, Austin, MN
Facility ID No. 28510
KSMQ Public Service Media, Inc.

Reduced Power STA Request

As previously reported to the Commission in a Reduce Power Notification (LMS File No. 0000129580), a fault has appeared in the KSMQ-TV transmitter that has made the transmitter forward power unable to be raised above 80%.

The problem has been diagnosed to have been caused by (1) the failure of a number of power amplifier modules and (2) a failed power supply. The licensee is currently working on repairing both the power amplifiers and the power supply. It is currently anticipated that full power will be restored in approximately 30 days.