

WSCG, Baxley, GA (Fac. Id. 69446)
Engineering STA Explanation

The WSCG transmitter suffered an equipment failure that has limited transmitter output so as to cause the station to operate at 20-25% of its licensed power. An assessment of the damage has been completed, and a decision has been made to replace the transmitter. Delivery and installation of the new transmitter is expected to take several weeks. During that time, WSCG requests temporary authority for up to 180 days to operate at 20-25% of its licensed power so that it can continue to provide some service to the public.