

Translators K250BV and K273CT have been silent since April 4, 2023, principally due to storm damage at the transmitter site- the site of KVTM which is itself operating pursuant to an STA because of the problems caused earlier this year by historic rain and resulting flooding at the transmitter site. The two translators are mounted on the KVTM main tower and work to repair the tower has been slowed due to the flooding and related damage, delayed insurance adjustor site visits, and other problems. The licensee has been examining alternatives for repairing KVTM and the translators and working with consulting engineers on these plans. Additional time is needed to complete this review and to return the translators to service.