

**Explanation for Reduced Power Operation**  
**K31KK-D**  
**Facility ID 51374**  
**Kingsville-Alice, TX**

The K31KK-D transmitter is malfunctioning and needs to be replaced. Due to limited space at the site, the station does not have a backup transmitter, so it has ceased operation. The removal of the existing transmitter and installation the new one is anticipated to take 12 days; however, station personnel will monitor the situation and K31KK-D will apply for a silent STA if it appears the replacement process will take longer than 30 days.