

### **Database Certification**

The antenna listed in the technical database is incorrect. The antenna is not an Andrew ATW20HSC-HSC3-21H. The installed antenna is a Dielectric TFU30DSC-200. The Dielectric antenna has a pattern which mimics that of the Andrew antenna. A license modification application is being filed to correct the antenna information in the technical database.