

## **EXHIBIT**

The licensee does not have a record of the method of structural analysis. An analysis was performed by a local Juneau engineering firm in 2004 that determined that the support structure, which is part of the building's roof system, could hold the weight of the new DTV antenna.