

Due to a transmitter failure, KUOK is temporarily silent. Replacement parts have been ordered and they are expected to be delivered shortly. While the Licensee hopes to be back on in less than 30 days, we respectfully request a period of 90 days in which to remain silent.