

DIRECTIONAL ANTENNA PATTERN

In the course of preparing the instant application, it was noted that two additional azimuths (124 and 242 degrees pre-rotation) are indicated in the directional antenna pattern data in the Antenna Technical Data section within the Licensing and Management System. These two additional azimuths appear to be associated with the antenna ID used for the original construction permit application. These two additional azimuths are not required for any reason, including interference protection. The applicant is unable to determine a means by which these erroneous and unnecessary additional azimuths can be removed in the Licensing and Management System. The pattern is, in all other aspects, accurate, and reflects the actual pattern of the constructed facility. It is requested that the license be granted without these two superfluous additional azimuths.