

New York Spectrum Holding Co.  
FRN 0021234943  
KVFW-LP, Facility ID 53433

As previously indicated the Station had a transmitter failure on January 31<sup>st</sup>. Licensee sent the part to the vendor for repair. The vendor has been unable to repair the malfunctioning part. In addition, the licensee was displaced in the spectrum auction and filed a displacement application for a new channel which remains pending. Even if repaired, the existing transmitter could not be used for the new channel. As such, licensee does not want to invest in a new transmitter until its displacement application is granted and it is certain what channel it will be on.