



402 Tenth Avenue • PO Box 367 • Haddon Heights, NJ 08035

Engineering Report
Amendment
September 2020

This amendment is to correct a typographical error in the longitude of the application.
The correct longitude is 90° 40' 15.6" West, correcting the minutes from 4 to 40.
All other portions of the application were based upon this now corrected value.