

Silent STA Request K15FJ-D

I visited the transmit site on April 2nd and found the 25 watt Superior Broadcast transmitter not working. When cycling power, it runs for a few minutes and then trips off. A new amplifier is being ordered to replace the defective one. I should be able to get it back up and running within two months.

Best Regards,

Keith Leitch
Engineer, One Ministries, Inc.