

LMS SYSTEM ERRATA

1. The LMS filing system computed an antenna HAAT of 23m horizontal, and 47.49m vertical even though the antenna height AMSL is identical for both polarizations. The LMS system does not allow manual correction of this data field. The correct HAAT for both polarities should be approximately 47.49m.

2. When modifying a licensed LPFM station, the LMS system apparently does not allow a modified entry for the antenna brand, model, number of antenna bays, or bay spacing. The application presented herein shows 2 bays with 0.8 wave spacing. The correct entry should be 2 bays with 0.75 wave-spacing, using a Bext TFC-2k antenna.

BROWN BROADCAST SERVICES
INCORPORATED

Michael D. Brown 3740 S.W. Comus St. Portland, Oregon 97219-7418 503-245-6065 mike@brownbroadcast.com