

**Explanation for Reduced Power Operation**  
**KJRH-TV**  
**Facility ID 59439**  
**Tulsa, OK**

KJRH-TV recently began experiencing difficulties maintaining full transmitter power. Station personnel have not yet been able to identify the cause of the problem. The station is currently maintaining 50% of its authorized power. The timetable to complete the repair is currently unknown; however, station personnel will monitor the situation and KJRH-TV will apply for an STA if it appears the repair process is anticipated to take longer than 30 days.