

Reason for STA Extension

KPLD is operating at reduced power due to a failed transformer and is currently operating with an effective radiated power of 2 KW. The licensee expects to have the replacement in a few weeks and respectfully request an extension of its current STA to continue operation at variance of its licensed parameters.