

JUSTIFICATION

Lightning appears to have struck nearby the tower and took down several components in the tower facility to include the transmitter amplifier. the tower light was also damaged but was repaired immediately. Licensee has a replacement transmitter being built as a replacement; however, it will be several weeks before the transmitter can be replaced.