

KOKC Oklahoma City, OK

Form 302-AM

License to Cover

December, 2023

prepared by:

**Michael Patton & Associates
Baton Rouge, Louisiana**

Reason for change in DA common point resistance:

The directional array common point resistance changed from its previous licensed value to accommodate modern transmitters' optimal load resistance of 50 Ohms.