

Basis for Extension

As previously reported to the Commission, station KBOB(AM) has been operating, day and night, with its nighttime antenna pattern due to an antenna switching issue (*See* FCC File Nos. BSTA-20220504AAF, BESTA-20221026AAD, and BESTA-20230615AAB). Townsquare installed a new RF contactor but after doing so discovered that additional components need to be replaced – including a failed antenna monitor. The antenna monitor has been returned to the manufacturer for repairs and calibration. In the interim, Townsquare respectfully requests an extension of the current STA.¹ Townsquare will promptly notify the Commission when the station is able to resume licensed operations.

¹ Due to difficulties resulting from conversion of the AM Station STA Form from CDBS to LMS, FCC staff has advised to file STA extension requests in this manner (i.e., as requests for use of an emergency antenna).