

KIQQ FM Silent STA extension

Efforts to repair the transmitter have been unsuccessful due to the inability to obtain all needed parts. It has been determined that a new transmitter will be required. Licensee does not yet have an official delivery date but has been advised that due to supply chain issues delivery could take several months.