

KSJI, St. Joseph, MO (Fac. Id. 81962)
Engineering STA Explanation

KSJI's transmitter failed on March 8, 2024 and can only provide a transmitter output power necessary to achieve an effective radiated power of 2.24 kilowatts, approximately 16% of its authorized ERP. A new transmitter has been ordered but will not arrive and be installed by the 30th day of reduced power operations. UNWSP respectfully requests authority to temporarily continue operating at reduced power for the earlier of 180 days or until such time as repairs are completed.