

JAMES B. HATFIELD, PE
BENJAMIN F. DAWSON III, PE
THOMAS M. ECKELS, PE
STEPHEN S. LOCKWOOD, PE
DAVID J. PINION, PE

PAUL W. LEONARD, PE
ERIK C. SWANSON, EIT
THOMAS S. GORTON, PE

HATFIELD & DAWSON
CONSULTING ELECTRICAL ENGINEERS
9500 GREENWOOD AVE. N.
SEATTLE, WASHINGTON 98103

TELEPHONE
(206) 783-9151
FACSIMILE
(206) 789-9834
E-MAIL
hatdaw@hatdaw.com

MAURY L. HATFIELD, PE
CONSULTANT
BOX 1326
ALICE SPRINGS, NT 5950
AUSTRALIA

APPLICATION for COORDINATE CORRECTION

KULE-AM

730 kHz

Ephrata, WA

Butterfield Broadcasting Corp

March 2004

This Engineering Statement is in support of an application by Butterfield Broadcasting Corp. to correct the coordinates for the licensed operation of KULE-AM, Ephrata, WA (Facility ID 4041). It was recently discovered that the KULE tower was not registered. In the course of obtaining FAA clearance for the tower, it was also discovered that the licensed coordinates are incorrect by six seconds of latitude and 7 seconds of longitude. A land surveyor was hired to determine the correct coordinates, and FCC Antenna Structure Registration has been completed. The ASR number of this tower is 1242715. This application seeks to correct the licensed coordinates of KULE-AM to correspond to the Antenna Structure Registration. No other changes are proposed.

Thomas S. Gorton P.E.
Consulting Engineer