

## **Request for Silent STA**

DKJCB has experienced microwave failure and path difficulties as well as component failure in the phasor used for directional operation.

KJCB will resume operation as soon as possible.