

Dale Bickel

From: Dale Bickel
Sent: Wednesday, May 01, 2019 7:30 AM
To: GSMITHWICK@FCCWORLD.COM
Subject: WYFZ BSTA-20190430AAL granted 5/1



Special Temporary Authority For a Radio Broadcast Station

Audio Division, Media Bureau

Date: May 1, 2019
File Number: BSTA-20190430AAL
Call Sign: WYFZ (FM)
Facility ID Number: 76441

For the reasons provided in the application request, Special Temporary Authority IS GRANTED for operation of the station above with parameters at variance to the license.

Given the circumstances described in the STA request and our review of the the minor change application BSTA-20190429ABF, we have no objection to WYFZ continuing to operate with 0.900 kW ERP maximum while that minor change application for corrections to licensed parameters is being processed.

The licensee is responsible for addressing any complaints of interference that may arise.

This STA authority expires **October 28, 2019**.

Authorized by: Dale Bickel dale.bickel@fcc.gov
Senior Electronics Engineer

A copy of this e-mail will be posted in the FCC's CDBS database under the file number above.
Please retain a copy of this authorization for your records.

Considerations:

Licensee must take all steps to ensure that workers and the public are not exposed to radiofrequency exposure in excess of the Commission's exposure limit.

This Special Temporary Authority does not supersede any non-FCC-regulated requirements applicable to the STA-authorized facility. The licensee remains solely and wholly responsible for maintaining compliance with such requirements.

Requests for extension of STA may be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.