



JAMES B. HATFIELD, PE
BENJAMIN F. DAWSON III, PE
THOMAS M. ECKELS, PE
STEPHEN S. LOCKWOOD, PE
DAVID J. PINION, PE

PAUL W. LEONARD, PE
ERIK C. SWANSON, EIT
THOMAS S. GORTON, PE

HATFIELD & DAWSON
CONSULTING ELECTRICAL ENGINEERS
9500 GREENWOOD AVE. N.
SEATTLE, WASHINGTON 98103

TELEPHONE
(206) 783-9151
FACSIMILE
(206) 789-9834
E-MAIL

hatdaw@hatdaw.com

MAURY L. HATFIELD, PE
CONSULTANT
BOX 1326
ALICE SPRINGS, NT 5950
AUSTRALIA

MULTIPLE OWNERSHIP SERVICE CONTOUR ANALYSIS

**Prepared for
Horizon Broadcasting Group, LLC
January 2005**

The attached analysis of compliance with the radio multiple ownership rules was prepared in accordance with the Rules and Regulations of the Federal Communications Commission, in connection with an assignment of license application for KWPK-FM Channel 281C2 Sisters, Oregon.

Unrated Market

KWPK-FM is located within the Bend, Oregon, market, as are all stations to be commonly-owned with which KWPK-FM has principal community contour overlap.

KWPK-FM	Channel 281C2	Sisters
KQAK(FM)	Channel 289C1	Bend
KLTW-FM	Channel 236C1	Prineville
KWLZ-FM	Channel 243C	Warm Springs
KRCO(AM)	690 kHz	Prineville

The Bend market is not rated by Arbitron. Therefore, analysis has been made consistent with the Commission's interim rules for unrated markets. The 70 dBu contours of FM stations were determined from the technical data contained in the most recent edition of the FCC FM Database. The listed antenna height above average terrain was used together with topographic data obtained from the digitized 30 second or 3 second database. The 5 mV/m daytime contours of AM stations were determined from the technical data contained in the most recent edition of the

FCC AM Database. The listed antenna parameter information was used together with a digitized version of the FCC M-3 or Region II ground conductivity database.

The service contours were plotted using correct map projection mathematics. Those stations whose transmitter sites are within the respective principal community service contours of the stations proposed to be commonly owned have only the sites rather than their contours shown. All contours and enclosed transmitter site locations have been labeled. A list of all stations considered is included with this statement.

In counting stations providing service to the "market" defined by each of the discrete clusters formed in unrated markets, stations whose transmitter sites are located in excess of 92 km from the perimeter of the common overlap area have been excluded, as have other stations to be commonly-owned but which do not have overlap with the discrete cluster being studied. This exhibit evidences at least the minimum number of stations necessary to demonstrate compliance with the rules concerning radio multiple ownership in unrated markets. Specifically, in order to qualify for common ownership of this 1AM/4FM cluster, there must be at least 15 stations in the relevant "market". This study demonstrates that there are at least 17 stations in the relevant market.

January 24, 2005

A handwritten signature in black ink, appearing to read "Erik C. Swanson". The signature is fluid and cursive, with the first name "Erik" and last name "Swanson" clearly distinguishable.

Erik C. Swanson

Hatfield & Dawson Consulting Engineers

**AM STATIONS WITH 5 mV/m CONTOURS OVERLAPPING
70 dBu CONTOURS OF KWPK-FM, KQAK(FM), KLTW-FM, KWLZ-FM
AND 5 mV/m CONTOUR OF KRCO(AM)**

Call Status	City St Co	FCC File No.	Freq Mode	Power(kW) Hrs Cls	Latitude Longitude
=====	=====	=====	=====	=====	=====
KRCO LIC	PRINEVILLE OR US	BL0000404ACK	690 ND2	1.000 DAY B	N 44-20-28 W 120-54-24
KICE LIC	BEND OR US	BL0020920ADV	940 DA2	10.000 DAY B	N 44-04-47 W 121-16-59
KBND LIC	BEND OR US	BL19970428AC	1110 DAN	10.000 DAY B	N 44-06-25 W 121-14-39

Hatfield & Dawson Consulting Engineers

**FM STATIONS WITH 70 dBu CONTOURS OVERLAPPING
70 dBu CONTOURS OF KWPK-FM, KQAK(FM), KLTW-FM, KWLZ-FM
AND 5 mV/m CONTOUR OF KRCO(AM)**

Call Status	City State	FCC File No.	Channel Freq.	ERP(kW) HAAT(m)	Latitude Longitude
KWRX LIC	REDMOND OR	BLD020612AAU	203C3 88.5	0.250 DA 670.0	44-26-14 120-57-12
KVLB LIC	BEND OR	BLD030730BCL	213A 90.5	0.500 172.0	44-04-40 121-19-48
KOAB-FM LIC	BEND OR	BLD860128KC	217C2 91.3	25.000 184.0	44-04-41 121-19-57
KXIX LIC	BEND OR	BLH860710KA	231C 94.1	100.000 303.0	44-02-48 121-31-53
KLTW-FM LIC	PRINEVILLE OR	BLH850916KA	236C1 95.1	100.000 144.0	44-18-32 120-55-47
KWLZ-FM LIC	WARM SPRINGS OR	BLH860127KG	243C 96.5	100.000 332.0	44-50-24 121-13-56
KNLR LIC	BEND OR	BLH850114LW	248C1 97.5	97.000 163.0	44-04-38 121-19-49
KTWS LIC	BEND OR	BLH950629KC	252C3 98.3	6.800 191.0	44-04-41 121-19-57
KTWS CP	BEND OR	BPH040405ABG	252C3 98.3	5.200 223.0	44-04-39 121-19-57
KMTK LIC	BEND OR	BLH041027ADJ	259C2 99.7	26.000 DA 208.0	44-04-39 121-19-57
KMGX LIC	BEND OR	BLH5892	264C1 100.7	50.000 158.0	44-04-40 121-19-49
KLRR LIC	REDMOND OR	BMLH990419KF	269C2 101.7	27.500 202.0	44-04-41 121-19-57
KLRR CP	REDMOND OR	BPH040405ABF	269C2 101.7	23.000 223.0	44-04-39 121-19-57
KSJJ LIC	REDMOND OR	BLH941108KA	275C1 102.9	100.000 270.0	44-02-48 121-31-53
KWPK-FM LIC	SISTERS OR	BLH010516AAI	281C2 104.1	34.000 180.0	44-04-40 121-19-49
KQAK LIC	BEND OR	BMLH010522AAO	289C1 105.7	40.000 180.0	44-04-40 121-19-49

Hatfield & Dawson Consulting Engineers

